

Apsekošanas kartīte

Vietējā ģeodēziskā tīkla punkts

Punkta veids: grunts zīme (gz)

Administratīvā adrese: Jūrmala,

Punkta atrašanās vietas apraksts: Mežā, apmēram 2m no takas un 50m no pludmales.

☒ normāls ☐ neatrasts☐ bojāts ☐ iznīcināts

Neatrašanas, iznīcināšanas iemesls:

Veicamie darbi

☐ Nav☐ Aprakuma
atjaunošana☐ Attīrīšana no apauguma☒ Uzstādīt norādītārstabinu ☐ Labot aizsargvāku☐ Markas urbuma atjaunošana☐ Nozāgēt koku

Citi veicamie darbi:

Punkta noformējums

☐ (AV) Aizsargvāks ☒ (K) Aprakums, kupica
☐ (N) Norādītājstabiņš ☐ (P) Piramīda
☐ (S) Signāls (tornis) ☐ (SS) Signālstabs

Redzamība ☐ Ir GP izmantojamība

Tiešā redzamība no 595:

Nav tiešās redzamības punktu.

Citas piezīmes:

Traucējumi punkta izmantošanā:

☐ Punkts atrodas nožogotā teritorijā, nav pieejams bez īpašnieka atļaujas

☐ Aizsargvāks nobīdīts, nevar nocentrēt Markas augstums no zemes virsmas (norādīts ar 5cm precizitāti): -5(cm)

☐ Traucē tuvumā
esošs obj., nevar
nocentrēt

☐ Punkts nošķiebts☐ Punkts applūst☐ Bojāta marka

☐ Punkts atrodas pārāk dziļi (-50cm)

☐ Markas urbums aizrūsējis

Citi traucējumi punkta izmantošanā: Nav

The map shows a landscape with a river at the top, a road in the middle, and a road at the bottom. A square symbol is located near the center, with the number 595 next to it. Other numbers include 7.2, 2.3, 30, 20, 15, 10, 5, 25, 40, and 2x1. There are also symbols for trees and a circle.

Apsekotājs: Kristis Celms Apsekošanas datums: 04.10.2013

Apsekotāja paraksts: